

Software Name: Firmware for IKS-G6824A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
-------------	------------------------------	--------------	-----------------	----------------------------	--------------------	------

Software Name: Firmware for IKS-G6824A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v5.6	Build_18110820	N/A	IKS-G6824A Series	<p>New Features:</p> <p>Layer 3:</p> <ol style="list-style-type: none"> Support tracking function. <p>Security Related Functions</p> <ol style="list-style-type: none"> System Notification: Definable successful/failed login notification. Password Policy: Password strength can be set. Account Lockout Policy: Failure threshold and lockout time can be set. Log Management: Full log handling. Remote Access Interface Enable/Disable. Configuration Encryption with password. Support SSL certification import. Support MAC authentication bypass via RADIUS authentication. MAC Address access control list or MAC address filtering. Protect against MAC flooding attack by MAC address sticky. NTP authentication to prevent NTP DDoS attack. Login Authentication: Support primary & backup database servers (RADIUS / TACACS+ / Local Account). Login Authentication via RADIUS Server: Support Challenge Handshake Authentication Protocol (CHAP) authentication mechanism. RADIUS Authentication: Support EAP-MSCHAPv2 (For Windows 7). MXview Security View Feature Support* (with MXstudio V2.4). 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Fix abnormal display of packet counter in the web GUI. When the device receives large amounts of BPDU packets on a port, the RSTP function does not enable, which might cause the device to reboot. If there is an '&' in either the Switch Name or Switch Location column, the description will not display properly on the relevant page. <p>Changes:</p> <ol style="list-style-type: none"> Rate limit adds more options on the ingress rate 	<p>Suggestion:</p> <ol style="list-style-type: none"> Reconfigure the device once you have upgraded to v5.x To ensure that the system remains stable, do not export configurations from v4.x or prior into v5.x or later

Software Name: Firmware for IKS-G6824A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
				Redundancy 1. Turbo Ring v2, Turbo Chain Support Port Trunking Enhancements: 1. Web GUI supports web browser Chrome 65.0 2. CLI: Supports Multiple Sessions (up to six). 3. SMTP Supports Transport Layer Security (TLS) Protocol and Removes SSL v2/v3. 4. SNMPv3 Traps and Informs. 5. Display Issues with Java Applet. 6. Fiber Check: Add Threshold Alarm. 7. Static Port Lock with VLAN filtering option. 8. When GbE Port Speed is [Auto], MDI/MDIX is [Auto] Fixed. 9. Web UI/CLI Command Enhancement and Modification.		
v4.5	Build_16112110	N/A	IKS-G6824A-20GSFP-4GTXSFP-HV-HV, IKS-G6824A-4GTXSFP-HV-HV, IKS-G6824A-8GSFP-4GTXSFP-HV-HV, IKS-G6824A-20GSFP-4GTXSFP-HV-HV-T, IKS-G6824A-4GTXSFP-HV-HV-T, IKS-G6824A-8GSFP-4GTXSFP-HV-HV-T	New Features: 1. Added DSCP remark function. 2. Added Traceroute function. Enhancements: 1. Encrypted all security passwords and keys in web user interface and the CLI.	Bugs Fixed: 1. VRRP did not work on RSTP ports. 2. VRRP state unexpectedly changed when it took too much time to change the IGMP querier. 3. VRRP state unexpectedly changed when both VRRP Fast Switchover mode is enabled and Port Trunking is set. 4. Configurations could not be imported through command line, when VRRP Fast Switchover mode is set with more than 16 entries. 5. Device occasionally rebooted when enabling OSPF. Changes: N/A	N/A

Software Name: Firmware for IKS-G6824A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v4.2	Build_15062312	N/A	IKS-G6824A-20GSFP-4GTXSFP-HV-HV, IKS-G6824A-4GTXSFP-HV-HV, IKS-G6824A-8GSFP-4GTXSFP-HV-HV, IKS-G6824A-20GSFP-4GTXSFP-HV-HV-T, IKS-G6824A-4GTXSFP-HV-HV-T, IKS-G6824A-8GSFP-4GTXSFP-HV-HV-T	<p>New Features:</p> <ol style="list-style-type: none"> Added new Multicast Fast Forwarding mode. Added new VRRP Fast Switchover mode. Added new Multicast Local Route. <p>Enhancements:</p> <ol style="list-style-type: none"> Increased IGMP Groups to 4096 (original 1000 groups). Improved Turbo Chain link status check mechanism at the head port. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Device rebooted when using CLI commands to back up device configurations to TFTP server. Device rebooted when using CLI commands to change SNMP v3 data encryption key and the length of key is over than 100 characters. <p>Changes:</p> <p>N/A</p>	N/A
v4.1	Build_15030209	N/A	IKS-G6824A-20GSFP-4GTXSFP-HV-HV, IKS-G6824A-4GTXSFP-HV-HV, IKS-G6824A-8GSFP-4GTXSFP-HV-HV, IKS-G6824A-20GSFP-4GTXSFP-HV-HV-T, IKS-G6824A-4GTXSFP-HV-HV-T, IKS-G6824A-8GSFP-4GTXSFP-HV-HV-T	<p>New Features:</p> <p>N/A</p> <p>Enhancements:</p> <p>N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> PIM-SM multicast forwarding issues. Randomly hang issue when booting up. Topology drawing issue on MXview. In IGMPv3, failed to forward multicast packets on MSTP DISABLED-STATUS port. Failed to add Static default route (0.0.0.0/0) through the web console. Randomly failed to recognize Moxa SFP modules. In OSPF routing protocol, 10 G ports had incorrect path cost. Randomly failed to connect to ABC-02. HTTPS certification validity issue. There was a rebooting issue when TFTP upgraded firmware with incorrect CLI command. ACL CLI command failed on rules when Ether-type is 0 or IP-protocol is 0. Hang issue when IGMP join and leave frequently. <p>Changes:</p> <p>N/A</p>	N/A

Software Name: Firmware for IKS-G6824A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v4.0	Build_14093015	N/A	IKS-G6824A-20GSFP-4GTXSFP-HV-HV, IKS-G6824A-4GTXSFP-HV-HV, IKS-G6824A-8GSFP-4GTXSFP-HV-HV, IKS-G6824A-20GSFP-4GTXSFP-HV-HV-T, IKS-G6824A-4GTXSFP-HV-HV-T, IKS-G6824A-8GSFP-4GTXSFP-HV-HV-T	New Features: 1. First release for IKS-G6824A Series. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A