

Software Name: Firmware for ICS-G7850A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
-------------	------------------------------	--------------	-----------------	----------------------------	--------------------	------

Software Name: Firmware for ICS-G7850A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v5.6	Build_18110819	N/A	ICS-G7850A Series	<p>New Features:</p> <p>Layer 3:</p> <ol style="list-style-type: none"> 1. Supports tracking function 2. Supports DSCP remark 3. Supports traceroute in CLI command <p>Security Related Functions</p> <ol style="list-style-type: none"> 1. System Notification: Definable successful/failed login notification. 2. Password Policy: Password strength can be set. 3. Account Lockout Policy: Failure threshold and lockout time can be set. 4. Log Management: Full log handling. 5. Remote Access Interface Enable/Disable. 6. Configuration Encryption with password. 7. Support SSL certification import. 8. Support MAC authentication bypass via RADIUS authentication. 9. MAC Address access control list or MAC address filtering. 10. Protect against MAC flooding attack by MAC address sticky. 11. NTP authentication to prevent NTP DDoS attack. 12. Login Authentication: Support primary & backup database servers (RADIUS / TACACS+ / Local Account). 13. Login Authentication via RADIUS Server: Support Challenge Handshake Authentication Protocol (CHAP) authentication mechanism. 14. RADIUS Authentication: Support EAP-MSCHAPv2 (For Windows 7). 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. Fix abnormal display of packet counter in the web GUI. 2. When the device receives large amounts of BPDU packets on a port, the RSTP function does not enable, which might cause the device to reboot. 3. If there is an '&' in either the Switch Name or Switch Location column, the description will not display properly on the relevant page. 4. If Turbo Chain is established on slot 9 it might not be stable. <p>Changes:</p> <ol style="list-style-type: none"> 1. Remove the VEE indicator on the PoE function 2. Rate limit adds more options on the ingress rate 	<p>Suggestion:</p> <ol style="list-style-type: none"> 1. Reconfigure the device once you have upgraded to v5.x 2. To ensure that the system remains stable, do not export configurations from v4.x or prior into v5.x or later

Software Name: Firmware for ICS-G7850A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
				<p>15. MXview Security View Feature Support* (with MXstudio V2.4).</p> <p>Redundancy 1. Turbo Ring v2, Turbo Chain Support Port Trunking</p> <p>Redundancy 1. Turbo Ring v2, Turbo Chain Support Port Trunking</p> <p>Enhancements:</p> <ol style="list-style-type: none"> 1. Web GUI supports web browser Chrome 65.0 2. CLI: Supports Multiple Sessions (up to six). 3. SMTP Supports Transport Layer Security (TLS) Protocol and Removes SSL v2/v3. 4. SNMPv3 Traps and Informs. 5. Display Issues with Java Applet. 6. Fiber Check: Add Threshold Alarm. 7. Static Port Lock with VLAN filtering option. 8. When GbE Port Speed is [Auto], MDI/MDIX is [Auto] Fixed. 9. Web UI/CLI Command Enhancement and Modification. 		

Software Name: Firmware for ICS-G7850A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v4.3	Build_16070716	N/A	ICS-G7850A-2XG-HV-HV	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. Fixed Fast VRRP instances with double Masters issue when enabling the loop protection function. 2. Fixed config import issue (ACL & Multicast local route). 3. If the switch had a PoE module and a SFP module, the SFP module may not link when rebooting. 4. Fixed L3 switch reboot when enabling OSPF. 5. VRRP (V-ON) was unstable when fiber port experienced link-down. 6. VRRP (V-ON) backup unit caused CPU to experience very high loading and the web UI was very slow. Changes: N/A	N/A
v4.2	Build_15062312	N/A	ICS-G7850A-2XG-HV-HV	New Features: 1. Added new Multicast Fast Forwarding Mode. 2. Added new VRRP Fast Switchover Mode. 3. Added new Multicast Local Route. Enhancements: 1. Increased IGMP Groups to 4096 (original 1000 groups). 2. Improved Turbo Chain link status check mechanism at the head port.	Bugs Fixed: 1. Device rebooted when it used CLI commands to back up device configurations to the TFTP server. 2. Device rebooted when using CLI commands to change SNMP v3 data encryption key and the length of the key is over 100 characters. Changes: N/A	N/A

Software Name: Firmware for ICS-G7850A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v4.1	Build_15030209	N/A	ICS-G7850A-2XG-HV-HV	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. PIM-SM multicast forwarding issues. 2. Randomly hang issue while booting up. 3. Flow control did not work on the ICS-G7850A Series. 4. Topology drawing issue on MXview. 5. In IGMPv3, forward multicast packets on MSTP DISABLED-STATUS port failed. 6. Failed to add Static default route (0.0.0.0/0) through Web console. 7. Randomly failed to recognize Moxa SFP modules. 8. In OSPF routing protocol, 10 G ports had incorrect path cost. 9. Randomly failed to connect to the ABC-02. 10. HTTPS certification validity issue. 11. Reboot issue while TFTP upgrading firmware with incorrect CLI command. 12. ACL CLI command failed on rules with Ether-type is 0 or IP-protocol is 0. 13. Hang issue while IGMP join and leave frequently. Changes: N/A	N/A
v4.0	Build_14093015	N/A	ICS-G7850A-2XG-HV-HV	New Features: 1. First release for the ICS-G7850A Series. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A