

## **Software Name:** Firmware for CN2510 Series (Rev. 3.x)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.1	Build 07081513	N/A	CN2510-8, CN2510-16, CN2610-8, CN2610-16	Supports RedundantCOM function for CN2610-8/16.  Enhancements: N/A	Bugs Fixed:  1. RIP packet could not be sent out via PPP & SLIP. (RDC07989)  2. AsyncServer's DHCP only sent DHCP requests twice. We modified the DHCP behavior; AsycServer will continue to send DHCP discover packets if there is no DHCP response. (RDC07971)  3. AsyncServer would not save the sender's MAC address if the target IP was not my IP. (RDC07943)  Changes: N/A	N/A
v3.0	N/A	N/A	CN2510-8, CN2510-16, CN2610-8, CN2610-16	N/A	Bugs Fixed:  1. Fixed accepting uni-directional software flow control. (v2.1.15)  2. Dial-in Mode TCP Compress enable issue. (v2.1.9)  3. Dial-in/Dial-out Mode Packet Fragmentation problem. (v2.1.7)  4. Direct cable connection issue for PPP mode. (v2.1.1)  Changes:  1. PPP Modification: Waits for client IPCP request first then sends out Server's ICPC Request. (v2.1.3)  2. PPP Modification: Improved IPCP negotiation, if receiving a request for DNS IP "0.0.0.0/255.255.255". (v2.1.3)	N/A