

Software Name: Firmware for VPort P16-1MP-M12-IR Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.4	Build_18030811	N/A	VPort P16-1MP-M12-IR-CAM36, VPort P16-1MP-M12-IR-CAM80, VPort P16-1MP-M12-IR-CAM36-T, VPort P16-1MP-M12-IR-CAM80-T, VPort P16-1MP-M12-IR-CAM36-CT, VPort P16-1MP-M12-IR-CAM80-CT, VPort P16-1MP-M12-IR-CAM36-CT-T, VPort P16-1MP-M12-IR-CAM80-CT-T	New Features: N/A Enhancements: 1. Upgraded the BIOS to v1.3. 2. Changed the serial no. to 12 digits in the web console.	Bugs Fixed: N/A Changes: N/A	N/A
v1.3	Build_17031716	N/A	VPort P16-1MP-M12-IR-CAM36, VPort P16-1MP-M12-IR-CAM80, VPort P16-1MP-M12-IR-CAM36-T, VPort P16-1MP-M12-IR-CAM80-T, VPort P16-1MP-M12-IR-CAM36-CT, VPort P16-1MP-M12-IR-CAM80-CT, VPort P16-1MP-M12-IR-CAM36-CT-T, VPort P16-1MP-M12-IR-CAM80-CT-T	New Features: N/A Enhancements: 1. Enhanced the tamper alarm function.	Bugs Fixed: 1. MXNVR-RO Discovery causing ONVIF process crash. 2. VMD & Tamper events not working on Genetec VMS. 3. Web server crash by Nessus Vulnerability Scanner. Changes: 1. Removed Timing info present from VUI. 2. Image sensor de-noise function on/off option. 3. Updated AWB algorithm.	N/A
v1.2	Build_16031718	N/A	VPort P16-1MP-M12-IR-CAM36, VPort P16-1MP-M12-IR-CAM80, VPort P16-1MP-M12-IR-CAM36-T, VPort P16-1MP-M12-IR-CAM80-T, VPort P16-1MP-M12-IR-CAM36-CT, VPort P16-1MP-M12-IR-CAM80-CT, VPort P16-1MP-M12-IR-CAM36-CT-T, VPort P16-1MP-M12-IR-CAM80-CT-T	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. Streaming server may not respond when taking a snapshot. 2. Camera webserver crashing when triggering CGI for a long time. 3. SOAP connection occasionally returning an HTTP 500 internal server error. Changes: 1. Improved VMS interoperability.	N/A