MOXA

Software Name: Firmware for EDS-408A Series (PN models)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.8	Build_17051216	N/A	EDS-408A-PN, EDS-408A-PN-T	**New Features:** N/A **Enhancements:** N/A	**Bugs Fixed:** 1. User account login authentication error in menu console mode. **Changes:** N/A	N/A
v3.7	Build_17031513	N/A	EDS-408A-PN, EDS-408A-PN-T	**New Features:** N/A **Enhancements:** 1. Added warning message when the default password was not changed. 2. Encrypted security keys in the user interface.	**Bugs Fixed:** 1. Cross-site scripting vulnerability. 2. Denial of Service attack vulnerability. 3. Privilege escalation vulnerability. 4. SSL v2/v3 vulnerability in HTTPS. 5. Web console could not be accessed due to SNMP get bulk. 6. Specific CLI command caused the switch to reboot with default settings. 7. Adding a new VLAN changed the IGMP querier state from disable to enable. 8. Saving configurations to the ABC-01 could not be performed via IE browser. 9. Rate limit cannot be set in web UI. 10. Telnet hangs after SSH disabled. 11. Corrected RSTP edge definition in exported configuration file. 12. Corrected authorization of Radius/TACACS+ login. 13. Corrected RSTP Auto-Edge behavior. 14. System sometimes rebooted after a period of operation when PROFINET was enabled. **Changes:** N/A	N/A
v3.2	Build_14121010	N/A	EDS-408A-PN, EDS-408A-PN-T	**New Features:** N/A **Enhancements:** N/A	**Bugs Fixed:** 1. Web user interface displayed errors under Java 8 environments. **Changes:** N/A	N/A

Software Name: Firmware for EDS-408A Series (PN models)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.1	N/A	N/A	EDS-408A-PN, EDS-408A-PN-T	**New Features:** 1. First release for the EDS-408A-PN Series. **Enhancements:** N/A	**Bugs Fixed:** N/A **Changes:** N/A	N/A