Software Name: ioMirror E3210 Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note
1.2	Build07121011	N/A	ioMirror E3210	New Features: 1. Added Locating I/O function in General Settings. 2. Added Modbus address function code=0x08 for "ECHO" function. 3. Counter overflow status is displayed on Channel Settings, and can be manually cleared. Enhancements: 1. Modify the length of "module loc" and "desc". 2. Modify the web console to add Alarm Mode function (blinking mode and do mode) on Web Mirror Settings page 3. Modify the web console to add Hold Last Status function on Web Do Channel Settings page.	Bugs Fixed: 1. Fix the connection problem that occasionally switching between on-line and off-line between ioMirror. 2. Fix the slow response problem while connecting to multiple ioMirror. 3. Fix the problem that reset the ioMirror will block the system after firmware upgrade. 4. Fix the problem that web console will not display all items. Changes: N/A	1. The firmware supports ioEventLog V1.1 only. 2. OS version: MOS V3.2.15A (modification of queue priority)
1.3	Build16052610	N/A	ioMirror E3210	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. Fixed DI return value reverse (Modbus Address 0x0000 to 0x0007) 2. Fixed peer-to-peer disconnection after about 3-month operation Changes: N/A	N/A

Software Name: ioMirror E3210 Firmware

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/Enhancements	Bugs Fixed/Changes	Note