Software Name: Driver for NPort S9650I Series (Linux 2.4 & 2.6)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.19	Build 17110917	Linux_2.4.x, Linux_2.6.x	NPort S9650I Series	**New Features:** 1. Add the driver background polling feature to eliminate the waiting time when the NPort does not exist in Slackware 14.0. **Enhancements:** 1. When using the domain name as a mapping address of an NPort, it will be translated every time when the Real TTY is opening the port. 2. Compiling errors when using the secured Real COM mode.	**Bugs Fixed:** 1. A call trace might occur with the error message "not syncing: Fatal exception" in kernel 2.6. 2. The compiling error will occur if the kernel version contains the string "2.4." 3. The Real TTY driver's installation and uninstallation fails due to insufficient permissions for the /tmp folder. **Changes:** 1. When the Log file increases without restrictions the file system crashes. 2. Does not support 3.x and above.	N/A