Tech Note 546Rebuilding a Corrupted InTouch® Managed Application (for versions
prior to InTouch 10.0 SP2)

All Tech Notes, Tech Alerts and KBCD documents and software are provided "as is" without warranty of any kind. See the Terms of Use for more information.

Topic#: 002289 Created: July 2008 Updated: January 2009

Introduction

Note: This *Tech Note* is **NOT** valid for InTouch 10.0 SP2 and later.

This *Tech Note* explains how to rebuild a corrupt InTouch Managed Application. The managed application can be corrupted in many ways. The following are common symptoms of a corrupted application:

- ArchestrA Symbols show the "RED X" in display at Runtime.
- WindowMaker[™] crashes when clicking on a window that has an ArchestrA Symbol.

There are two ways to recover a corrupted Managed InTouchViewApp:

- 1. Rebuild the Original InTouchViewApp.
- 2. Create a New Derived InTouchViewApp and Import From the Corrupted InTouchViewApp.

Application Versions

- InTouch 10.0 to InTouch 10.0 SP1
- Wonderware Application Server 3.0 to Wonderware Application Server 3.0 SP1

Rebuild the Original InTouchViewApp

This section explains rebuilding the original InTouchViewApp.

- 1. Ensure that the template has all the graphics in WindowMaker, then check-in the InTouchViewApp.
- 2. Copy the CheckedIn folder located at

C:\Program Files\ArchestrA\Framework\FileRepository\YourGalaxyName\ObjectFileStorage \\$YourInTouchViewApp to another new location. Figure 1 (below) shows the default location before copying.

😂 C:\Program Files\ArchestrA\Framework\FileRepository\Test\ObjectFileStorage\\$InTouchViewApp_001					
Eile Edit View Favorites Tools Help					
🔇 Back 🔻 🕥 🖌 🏂 🔎 Search 🎓 Folders 🔯 🌶 🗙 🌱 🛄					
Address 🛅 C:\Program Files\ArchestrA\Framework\FileRepository\Test\ObjectFileStorage\\$InTouchViewApp_001 💽 🕞 Go					
Folders	×	Name 🔺	Size	Туре	
🖃 🥯 Local Disk (C:)				File Folder	
a \$RECYCLE.BIN		CheckedOut		File Folder	
🛨 🧰 Boot					
🗉 🗀 CENTENN.IAL					
🛨 🧰 Debugger					
🕀 🛅 dell					
E COVERY					
Documents and Settings					
🖅 🚞 Dumps					
🗀 HF1014					
perflogs					
🖃 🧰 Program Files					
🖅 🛅 Adobe					
🖃 🧰 ArchestrA					
🖃 🚞 Framework					
🛨 🧰 Bin					
🛨 🧰 Docs					
🖃 🚞 FileRepository					
🗉 🚞 IMF5_GR01					
🖃 🧰 Test					
BaseTemplatePDFs					
🗆 🚞 ObjectFileStorage					
E 🗁 \$InTouchViewApp_001					
🗆 🗀 CheckedIn					
Symbols	•	•		Þ	

Figure 1: Default CheckedIn File Location

- 3. Open WindowMaker in the InTouchViewApp that has the problem.
- 4. Delete *all* the Windows in WindowMaker.
- 5. In the main menu, click **Special/Do Update Use Count**.
- 6. Click Yes (Figure 2 below).



Figure 2: Use Count Prompt

- 7. Check-in the InTouchViewApp.
- 8. Open the InTouchViewApp in WindowMaker.
- 9. Import all the Windows from the **CheckedIn** folder which you saved to a new location in step #2.

Application Data Import Op	tions	
Application: C:\Program Files	\ArchestrA\Fra	mework\FileR
Import Options		Import
✓ Windows	Select	Connect
🔲 Data Change Scripts	Select	
🗖 Key Scripts	Select	
Condition Scripts	Select	
□ <u>Q</u> uickFunctions	Select	
ActiveX Event Scripts		
□ Application Script		
Use Existing Tags (Conserv	e Placeholdersj)

- 10. Switch to WindowViewer[™] and ensure that all the windows show their graphics.
- 11. Check-In the InTouchViewApp again.
- 12. Now deploy the instance to all the nodes required.

You should see all the necessary graphics.

This section explains rebuilding the original InTouchViewApp using a new derived InTouchViewApp. During the task you import all windows and scripts from the corrupted application using DB Load.

1. Copy the CheckedIn folder located at

C:\Program Files\ArchestrA\Framework\FileRepository\YourGalaxyName\ObjectFileStorage \\$YourInTouchViewApp to another new location (Figure 1 above).

- 2. Do a **DB Dump** on the InTouchViewApp that has the problem so that you can get the tagname dictionary. To do the DB Dump, right-click the InTouchViewApp and click **Export/DB Dump**.
- 3. Save the **.csv** file to a location where you can retrieve it later.
- 4. Create a new derived InTouchViewApp.
- 5. Open WindowMaker, then close it.
- 6. Check in the new derived InTouchViewApp.
- 7. Do a DB Load on the new derived InTouchViewApp. To do a DB Load, right click on the InTouchViewApp and click Import/DB Load.
- 8. Select the **.csv** file you saved in #3 above.
- 9. Check In the InTouchViewApp when prompted.
- 10. Open the InTouchViewApp in WindowMaker.
- 11. Import all the Windows and all the scripts from the checked in folder you copied to a new location in step #1.
- 12. When the Application Data Import Options dialog box appears, check the Use Existing Tags (Conserve Placeholders) option (Figure 3 below).

If any scripts or windows are in the corrupted application you can select the scripts or windows. If the application has no scripts the check box fields will show as grayed out.

Application Data Import Options					
Application: C:\Program Files	VArchestrA\Fram	ework\FileR			
Import Options		Import			
<u> </u>	Select	Canaal			
Data Change Scripts	Select				
☐ Key Scripts	Select				
Condition Scripts	Select				
QuickFunctions	Select				
ActiveX Event Scripts					
Application Script					
Use Existing Tags (Conserve Placeholders)					

Figure 4: Application Data Import Options

- 13. Switch to WindowViewer and ensure that all the windows show their graphics.
- 14. Check-In the InTouchViewApp.
- 15. Deploy the instance to all the nodes required.

You should see all the necessary graphics.

Additional Resources

InTouch Managed Application Tech Alerts

In order to rebuild the corrupt application successfully with InTouch 10.0 SP2, the following MUST BE completed:

You **MUST** run the ArchestrA Symbol Analysis and Repair Utility for SP1, and have *no errors and no warnings* in the SMC logger after running both the tabs (**Duplicate ID** and **InTouchViewApp Embedded**) in the utility, *before you migrate to InTouch 10.0 SP2*. Then, follow the steps in Tech Note 570 by clicking the following link:

- Tech Note 570 Rebuilding a Corrupted InTouch® Managed Application for InTouch versions 10.0 SP2 (for versions *later than* InTouch 10.0 SP2)
- 107 Potential Safety Issue When Using ArchestrA Symbols Embedded in InTouch® 10.0 Applications
- 108 ArchestrA Symbol Analysis and Repair Utility Supplemental Information
- 109 Potential Safety Issue Incorrect Symbol May Be Displayed When Using ArchestrA Symbols Embedded in InTouch® 10.0 Applications

Tech Notes are published occasionally by Wonderware Technical Support. Publisher: Invensys Systems, Inc., 26561 Rancho Parkway South, Lake Forest, CA 92630. There is also technical information on our software products at Wonderware Technical Support.

For technical support questions, send an e-mail to support@wonderware.com.



© 2009 Invensys Systems, Inc. All rights reserved. No part of the material protected by this copyright may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying, recording, broadcasting, or by anyinformation storage and retrieval system, without permission in writing from Invensys Systems, Inc. Terms of Use.