

Software Name: Firmware for EDS-405A Series (PN models)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.8	Build_17051216	N/A	EDS-405A-PN, EDS-405A-PN-T	<p>New Features: N/A</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: 1. User account login authentication error in menu console mode.</p> <p>Changes: N/A</p>	N/A
v3.7	Build_17031513	N/A	EDS-405A-PN, EDS-405A-PN-T	<p>New Features: N/A</p> <p>Enhancements:</p> <ol style="list-style-type: none"> Added warning message when default password was not changed. Encrypted security keys in user interface. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Cross-site scripting vulnerability. Denial of Service attack vulnerability. Privilege escalation vulnerability. SSL v2/v3 vulnerability in HTTPS. Web console cannot be accessed when the SNMP get bulk service is running. Specific CLI command caused the switch to reboot with default settings. Adding a new VLAN changed the IGMP querier state from disabled to enabled. Saving configurations to ABC-01 cannot be performed via IE browser. Rate limit cannot be set in web UI. Telnet hangs when SSH is disabled. Correct RSTP edge definition in exported configuration file. Correct authorization of Radius/TACACS+ login. Correct RSTP Auto-Edge behavior. System sometimes rebooted after a period of operation while PROFINET is enabled. <p>Changes: N/A</p>	N/A
v3.2	Build_14121009	N/A	EDS-405A-PN, EDS-405A-PN-T	<p>New Features: N/A</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: 1. Web user interface displayed errors under Java 8 environments.</p> <p>Changes: N/A</p>	N/A

Software Name: Firmware for EDS-405A Series (PN models)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.1	N/A	N/A	EDS-405A-PN, EDS-405A-PN-T	New Features: 1. First release for EDS-405A-PN Series. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A