

## Software Name: Firmware for PT-7710 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.8	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-LV	New Features: N/A  Enhancements: 1. Added warning message when the default password was not changed. 2. Encrypted security keys in user interface. 3. Enhanced RSTP compatibility.	Bugs Fixed:  1. Cross-site scripting vulnerability. 2. Denial of service attack vulnerability. 3. Privilege escalation vulnerability. 4. SSL v2/v3 vulnerability in HTTPS. 5. Web console cannot be accessed when the SNMP get bulk service is running. 6. Specific CLI command cause switch reboot with default settings. 7. Added a new VLAN will change IGMP querier state from disable to enabled. 8. Saving configuration to ABC-01 cannot be performed via IE browser. 9. Corrected RSTP auto-edge behavior. 10. Rate limit cannot be set in web UI. 11. PTP timestamp error in announce message. 12. Display issue with JAVA applet. 13. Telnet hangs after SSH disabled. 14. Corrected RSTP edge definition in exported configuration file. 15. Corrected authorization of Radius/TACACS+ login. Changes: N/A	N/A
v3.3	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-LV	New Features: N/A Enhancements: N/A	Bugs Fixed:  1. Fixed MDIX and MDI port status setting issue.  2. Fixed CLI mode log in issue.  3. Added Hybrid VLAN setting function in CLI mode.  4. Fixed SNTP server cannot send NTP V1 packet issue.  Changes:  N/A	N/A

Form number: HQ-PD.450 Version: v3.8 Page 1 of 3



## **Software Name:** Firmware for PT-7710 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.1	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-LV	New Features: N/A  Enhancements: 1. Passed ODVA EtherNet/IP certificate. 2. Added some minor SNMP OIDs. 3. Enhanced multicast performance. 4. Added version number in MIB file.	Bugs Fixed:  1. NTP did not synchronize time in default settings.  2. NTP client function did not work with Windows XP NTP server.  3. Firmware Upgrade Failed when IEEE 802.1x was enabled.  4. Switch rebooted when receiving IGMP v3 packets (commonly used in Windows 7).  Changes:  N/A	N/A
v3.0	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-HV, PT-7710-D-LV	New Features:  1. RSTP-2004. 2. MSTP. 3. NTP Server/Client. 4. SW 1588 PTPv2. 5. CLI. 6. Ethernet/IP. 7. Hybrid VLAN. 8. Radius/TACACS+ for both login access and port authentication. 9. Egress rate limit. 10. Unknown unicast filtering. 11. CPU loading. 12. Change IP without reboot. 13. DHCP Discover retries forever, or retries for a period of time. 14. GARP timer adjustment. 15. Loop-protection. 16. Link Fault Shutdown. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A

Form number: HQ-PD.450 Version: v3.8 Page 2 of 3



Software Name: Firmware for PT-7710 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.6	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-LV	New Features: 1. Added 10FL and MTRJ module.  Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
v1.2	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-LV	New Features:  1. Supports TurboPack™ 2009 (add new functions for Turbo Chain, IPv6, Modbus/TCP, IEEE 1588 PTP, SNMP Inform, LLDP, DHCP Option 82, Firefox, and SSH).  2. Note: If you want to upgrade to the latest firmware, please refer to the PT-7710 user manual page 3-10 "System File Update" for detailed instructions.  Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
v1.1	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-LV	New Features:  1. Added PM-7200-8SFP compatibility function. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
v1.0	N/A	N/A	PT-7710-F-HV, PT-7710-F-LV, PT-7710-D-HV, PT-7710-D-LV	New Features:  1. New release for the PT-7710 Series. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A

Form number: HQ-PD.450 Version: v3.8 Page 3 of 3