

Software Name: Driver for NPort S8000 Series (Real TTY for Linux 2.4.x, 2.6.x)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
1.19	N/A	Linux_2.4.x, Linux_2.6.x	N/A	New Features:	Bugs Fixed:	N/A
				Added driver background polling feature to eliminate the waiting time when an NPort is not present in Slackware 14.0.	A call trace may happen with the error message "not syncing: Fatal exception" in kernel 2.6 for specific platforms. Compiling error if the kernel version contains the stream "2.4."	
				Enhancements:	3. Real TTY driver installation and uninstallation fails due	
				When using a domain name as the mapping address for NPort, it will be translated every time when Real TTY is opening the port. Compiling errors when using secured Real COM mode.	to insufficient permissions for the /tmp folder. Changes: 1. Log file increasing without limit causes a file system crash. 2. No longer supports 3.x and above.	