

Software Name: Driver for UPort 2210/2410 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
-------------	------------------------------	--------------	-----------------	----------------------------	--------------------	------

Software Name: Driver for UPort 2210/2410 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.0	N/A	Mac_OS_X	UPort 2210, UPort 2410	<p>New Features: First release</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	<p>For Mac OS X 10.4 to 10.8 (x86/x64)</p> <p>Steps:</p> <ol style="list-style-type: none"> 1. Shut down your Mac. 2. Power on and boot to Recovery OS by holding down the Command and R keys at startup. 3. Launch Terminal from the Utilities menu. 4. In Terminal, enter the following command: \$ csrutil disable 5. Reboot the system. 6. Click driv_osx_uport2000_v1.0_build_12112817.dmg and follow the instructions to install the driver. 7. Launch Terminal from the Utilities menu. Enter the following command to verify the installation: \$ ls /dev/cu.USB* <p>Official reference for Configuring System Integrity</p>

Software Name: Driver for UPort 2210/2410 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
						Protection: https://developer.apple.com/library/archive/documentation/Security/Conceptual/System_Integrity_Protection_Guide/ConfiguringSystemIntegrityProtection/ConfiguringSystemIntegrityProtection.html#/apple_ref/doc/uid/TP40016462-CH5-SW1