

Software Name: Driver for CP-114EL Series (WinCE 5)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
1.1	N/A	Windows_CE_5.0	N/A	<p>New Features: Supports multiple MOXA Smartio/Industio PCI and PC/104-Plus cards.</p> <p>Enhancements: Improved latency time.</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. Fixed timeout error when a transaction is busy. 2. Fixed errors when setting software flow control. 3. Fixed the system not updating modem status immediately. 4. Fixed the system hanging when the setting of software follow control is disabled. <p>Changes: N/A</p>	N/A