

Software Name: Driver for CP-132UL Series (Windows XP, 2008 or earlier)

| Version No. | Build Date No./<br>Release Date | Supported OS  | Apply to Models | New Features/ Enhancements          | Bugs Fixed/Changes  | Note |
|-------------|---------------------------------|---|-----------------|-------------------------------------|---|------|
| v1.24       | N/A                             | Windows_2000, Windows_Server_2003, Windows_Server_2008, Windows_Vista, Windows_XP         | N/A             |                                     | Bugs Fixed:  1. Data transmission error in Windows 10 for PCIe cards.  2. RTS toggle not working for PCIe boards.  3. While installing PC/104 and ISA cards, the model name might not be found when using the "Add New Hardware Wizard".  4. The software kept cancelling read commands, which caused a BSOD.  5. When the system boots up with CP134EL-A-I, CP138E-A-I, CP118E-A-I, and CP-116E-A, serial communication might fail randomly.  Changes:  Windows XP is not included in WHQL support list due to the updated Windows rule. | N/A  |
| v1.24       | N/A                             | Windows XP,Windows<br>2000,Windows<br>Vista,Windows Server<br>2008,Windows Server<br>2003 | N/A             | New Features: N/A Enhancements: N/A | Bugs Fixed: N/A Changes: N/A  | N/A  |