

Software Name: Firmware for OnCell G3100-HSPA Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
1.7	N/A	N/A	OnCell G3110-HSPA/OnCell G3150-HSPA	Function to enable/disable configuration of Moxa services in web and telnet consoles. The area of the services and telnet consoles. The area of the services are services.	Bugs Fixed: 1. Handling of invalid HTTP packets: New mechanism to handle invalid HTTP packets. Changes: N/A	N/A
v1.6	N/A	N/A	N/A	N/A Enhancements:	Bugs Fixed: N/A Changes: N/A	N/A