

Software Name: Firmware for OnCell G3101/G3201 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
1.9	N/A	N/A	OnCell G3111/OnCell G3151/OnCell G3211/OnCell G3251	New Features: 1. New web cookie to avoid CSRF attacks. 2. Account lock mechanism to protect against multiple failed logins. 3. Function to enable/disable configuration of Moxa services in web and telnet consoles. Enhancements: 1. Higher web login cookie size and additional components for increased login security.	Bugs Fixed: 1. Invalid web packet causing device to reboot. 2. New mechanism to handle invalid HTTP packets. Changes: 1. When the user account is idle for more than 5 minutes while logged into the web console, the login times out and user will need to login again.	N/A
v1.8	N/A	N/A	N/A	New Features: N/A Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A