

Software Name: MXIO Library for Windows

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.12	Build16101215	Windows_10, Windows_7, Windows_8.1, Windows_Server_2003, Windows_Server_2008, Windows_Server_2012	ioLogik 4000 Series, ioLogik W5340-HSPA Series, ioLogik E2200 Series, ioLogik R2100 Series, ioLogik E1200 Series, ioLogik E1200H Series, ioLogik E1500 Series, ioLogik R1200 Series	<p>New Features:</p> <p>1. Added APIs for AI & AO 0-20mA Mode of ioLogik E1200 Series: E1K_AI_ReadMins, E1K_AI_ReadMaxs.</p> <p>Enhancements:</p> <p>1. Added End User License Agreement. 2. Support ioLogik E1200 password length to 16 and backward compatible to old firmware.</p>	<p>Bugs Fixed:</p> <p>1. Updated help file for E2210 to support DO command. 2. Updated the following APIs in help file to support E2242/E2260/E2262 Models: Pulse2K_GetSignalWidths32, Pulse2K_SetSignalWidths32, Pulse2K_GetSignalWidth32, Pulse2K_SetSignalWidth32.</p> <p>Changes:</p> <p>N/A</p>	N/A
v2.11	Build14011416	Windows_2000, Windows_7, Windows_Server_2003, Windows_Server_2008, Windows_XP	ioLogik W5340-HSPA Series, ioLogik 4000 Series, ioLogik E2200 Series, ioLogik R2100 Series, ioLogik E1200 Series, ioLogik E1200H Series, ioLogik E1500 Series, ioLogik R1200 Series	<p>New Features:</p> <p>N/A</p> <p>Enhancements:</p> <p>N/A</p>	<p>Bugs Fixed:</p> <p>1. Fixed connection failure issue for ioLogik E2210 and ioLogik E22.</p> <p>Changes:</p> <p>N/A</p>	N/A
v2.10	Build13091318	Windows_2000, Windows_7, Windows_Server_2003, Windows_Server_2008, Windows_XP	ioLogik W5340-HSPA Series, ioLogik 4000 Series, ioLogik E2200 Series, ioLogik R2100 Series, ioLogik E1200 Series, ioLogik E1200H Series, ioLogik E1500 Series, ioLogik R1200 Series	<p>New Features:</p> <p>1. Supports these new modules: ioLogik E1213, ioLogik R1210, ioLogik R1212, ioLogik R1214, ioLogik R1240, ioLogik R1241.</p> <p>Enhancements:</p> <p>N/A</p>	<p>Bugs Fixed:</p> <p>N/A</p> <p>Changes:</p> <p>N/A</p>	N/A