

Software Name: **Windows XP Embedded Driver**

| Version No. | Build Date No./ Release Date | Supported OS | Apply to Models | New Features/Enhancements | Bugs Fixed/Changes | Note |
|-------------|------------------------------|---------------------|---|---|---|------|
| 1.14 | Build 11042017 | Windows XP Embedded | CN2500 Series: CN2510-8, CN2510-16, CN2510-8-48V, CN2510-16-48V CN2600 Series: CN2610-8, CN2610-16, CN2650-8, CN2650-16, CN2650I-8, CN2650I-16, CN2610-8-2AC, CN2610-16-2AC, CN2650-8-2AC, CN2650-16-2AC, CN2650I-8-2AC, CN2650I-16-2AC NPort: DE-211, DE-311, DE-311M, DE-301, DE-302, DE-304, DE-334 NPort 5100 Series: 5110, 5130, 5150, 5110A, 5130A, 5150A NPort 5200 Series: 5210, 5230, 5232, 5232I, 5210A, 5230A, 5250A NPort 5400 Series: 5410, 5410 V3, 5430, 5430 V3, 5430I, 5430I V3, 5450, 5450I NPort 5600 Rackmount Serie: 5610-8, 5610-16, 5610-8-48V, 5610-16-48V, 5630-8, 5630-16, 5650-8, 5650-16, 5650-8-M-SC, 5650-16-M-SC, 5650-8-S-SC, 5650-16-S-SC NPort 5600 Desktop Series: 5610-8-DT, 5610-8-DT-J, 5650-8-DT, 5650I-8-DT, 5650-8-DT-J NPort 5600 Desktop Lite Series: 5610-8-DTL, 5650-8-DTL, 5650I-8-DTL NPort IA Series: IA-5150, IA-5150I, IA-5150-S-SC, IA-5150I-S-SC, IA-5150-M-SC, IA-5150I-M-SC, IA-5250, IA-5250I, IA5450A, IA5450AI, IA5150A, IA5150AI, IA5250A, IA5250AI NPort 6000 Series: 6150, 6250, 6250-M-SC, 6250-S-SC, 6450, 6650-8, 6650-16, 6610-8, 6610-16, 6610-32, 6650-32 NPort S8000 Series: NPort S8455I-MM-SC, NPort S8455I-SS-SC, NPort S8455I, NPort S8458-4S-SC-T NPort Wireless Series: W2004, W2150, W2250, W2150 Plus. | New Features: 1. Support NPort S8458-4S-SC-T. 2. Support NPort 5600 DTL series. 3. NPort driver will agree to open COM port on the system even if the port is blocked or the Ethernet connection is disabled. Enhancements: 1. N/A | Bugs Fixed: 1. DE-2XX and DE-3XX series cannot be searched if the number of devices is more than four. 2. NPort device cannot be found by utility via wireless network adapter under Windows Vista/7. 3. Driver causes system BSOD by writing to an invalid memory location under Windows 2008 64bit. 4. The application will not work properly when login with standard user in Windows Vista/7 environment. This version will prompt user change to account with administration rights. Changes: 1. N/A | N/A |