



## Software Release Note

Software Name: IKS-6728/6726 Series Firmware

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
3.4	Build_15010917	N/A	IKS-6728-4GTXSFP IKS-6726-2GTXSFP	N/A	1. Web user interface display errors under Java 8 environment.	N/A	N/A	N/A
3.3	N/A	N/A	IKS-6728-4GTXSFP IKS-6726-2GTXSFP	N/A	N/A	1. Add web interface for loop-protection enable/disable. 2. Add web interface for SSH/SSL key generation. 3. Add SNMP MIB for SFP DDM (Diagnostics). 4. Add SNMP MIB for Hybrid VLAN.	1. Login fail in CLI mode when password is with special character 2. SFP DDM display inaccurate values 3. IEEE 1588 PTP cannot function correctly 4. Far-end fault fails on 100M fiber port 5. Restricts configuration import if the system name is too long 6. Login authentication failed if the radius server does not support privilege levels assignment 7. Network looping when IPv6 based computer connects to Turbo Chain network 8. Turbo Chain unstable operation after power rebooting 9. Potential multicast traffic loss on gigabit fiber ports 10. LLDP error when changing management VLAN setting	N/A
3.1	N/A	N/A	IKS-6728-4GTXSFP IKS-6726-2GTXSFP	N/A	N/A	1. Pass ODVA EtherNet/IP certificate 2. Add some minor SNMP OIDs 3. Enhance multicast performance 4. Add version number in MIB file	1. NTP cannot synchronize time in default setting 2. NTP client function cannot work with Windows XP NTP server 3. Firmware Upgrade Failed when IEEE 802.1x is enabled 4. Switch reboots when receiving IGMP v3 packets (commonly used in Windows 7)	N/A
3.0	N/A	N/A	IKS-6728-4GTXSFP IKS-6726-2GTXSFP	Newly released for IKS-6726/6728 Series	N/A	N/A	N/A	N/A