


NI15-P30SR-VP4X2 Inductive Sensor




Technical data



Features



Wiring diagram



Functional principle






Technical data	

Mounting instructions

Mounting instructions/Description






6947216

6901319


Accessories

/ (CCC33011C.




Quick-mount bracket with dead-stop; material: Chrome-plated brass. Male thread M36 × 1.5. Note: The switching distance of the proximity switches may change when using quick-mount brackets.


6945103



Mounting clamp for threaded barrel sensors, with dead-stop; material: PA6



6945005 Mounting bracket for threaded barrel sensors; material: Stainless steel A2 1.4301 (AISI 304)



Mounting clamp for smooth and threaded barrel sensors; material: Polypropylene