

Software Name: Firmware for EDS-405A Series (PTP models)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.8	Build_17041115	N/A	EDS-405A-PTP	New Features: N/A Enhancements: 1. Add warning message when default password was not changed. 2. Encrypt security keys in user interface.	Bugs Fixed: 1. Cross-site scripting vulnerability. 2. Denial of Service attack vulnerability. 3. Privilege escalation vulnerability. 4. SSL v2/v3 vulnerability in HTTPS. 5. Web console cannot be accessed due to SNMP get bulk. 6. Specific CLI command caused switch to reboot with default settings. 7. Adding a new VLAN changed IGMP querier state from disabled to enabled. 8. Saving configurations to ABC-01 could not be performed via IE browser. 9. Rate limit could not be set in web UI. 10. Telnet hangs after SSH disabled. 11. Correct RSTP edge definition in exported configuration file. 12. Correct authorization of Radius/TACACS+ login. 13. Correct RSTP Auto-Edge behavior. 14. System could only reboot after a period of operation while PROFINET was enabled. 15. After the firmware has been upgraded, the system sometimes performed a warm start when the user logged in to the switch. Changes: N/A	N/A
v3.5	Build_15040918	N/A	EDS-405A-PTP	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. Ethernet ports auto-negotiation fail at 10 M speed. 2. 1588 PTP time synchronization failed after rebooting grandmaster clock. 3. Unable to configure system name via SNMP. Changes: N/A	N/A

Form number: HQ-PD.450 Version: v3.8 Page 1 of 2



Software Name: Firmware for EDS-405A Series (PTP models)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v3.3	N/A	N/A	EDS-405A-PTP	New Features:	Bugs Fixed:	N/A
				1. First release for EDS-405A-PTP	N/A	
				Series.		
				Enhancements:	Changes:	
				N/A	N/A	