

Software Name: Firmware for EDS-408A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.6	N/A	N/A	EDS-408A-MM-ST-T, EDS-408A-T, EDS-408A-3S-SC-48-T, EDS-408A-3M-SC-T, EDS-408A-EIP, EDS-408A-2M1S-SC-T, EDS-408A-3M-ST-T, EDS-408A-EIP-T, EDS-408A-1M2S-SC-T, EDS-408A-MM-SC-T, EDS-408A, EDS-408A-MM-ST, EDS-408A-MM-SC, EDS-408A-SS-SC, EDS-408A-3M-ST, EDS-408A-3M-SC, EDS-408A-3S-SC, EDS-408A-3S-SC-48, EDS-408A-1M2S-SC, EDS-408A-2M1S-SC, EDS-408A-SS-SC-T, EDS-408A-3S-SC-T	New Features: 1. Supports TurboPack™ 2009 (Add the new managed functions of Turbo Chain, IPv6, Modbus/TCP, IEEE 1588 PTP, SNMP Inform, LLDP, DHCP Option 82, Firefox, and SSH) Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	For products with firmware prior to v2.6, users must upgrade to v2.6 before upgrading to the latest v3.X firmware.
v2.2	N/A	N/A	EDS-408A Series	New Features: 1. New firmware release for the EDS-408A Series with three fiber ports. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
v2.1	N/A	N/A	EDS-408A Series	New Features: 1. Added new Turbo Ring ("Turbo Ring V2") function. 2. Added new Ring Coupling function. 3. Added Daylight Saving function. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A

Software Name: Firmware for EDS-408A Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.3	N/A	N/A	EDS-408A Series	New Features: 1. Added Syslog Function. 2. Added Restart Function. 3. Supports ABC-01. 4. Changed default setting of Flow Control from Enable to Disable. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A
v1.1	N/A	N/A	EDS-408A Series	New Features: 1. New firmware release for the EDS-408A Series. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A