

Software Name: Firmware for PT-G503 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v4.3	Build_17090110	N/A	PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV	<p>New Features: N/A</p> <p>Enhancements:</p> <ol style="list-style-type: none"> 1. PTP: Supports BC/TC P2P/E2E. 2. PTP: Supports Power profile. 3. PTP: Supports 2-step to 1-step. 4. IEC 62439-3: Configurable supervision frame. 5. Security: Added a warning message for when the default password has not changed yet. 6. Security: Encrypts security keys in the user interface. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. Cross-site scripting vulnerability. 2. Denial of Service attack vulnerability. 3. Privilege escalation vulnerability. 4. SSL v2/v3 vulnerability in HTTPS. 5. Web console cannot be accessed when the SNMP get bulk service is running. 6. Specific CLI command caused the switch to reboot with default settings. 7. PTP timestamp error in announce Message. 8. System rebooted after specific CLI commands. 9. Telnet hangs when SSH is disabled. 10. For PT-G503 models that use SFP-1G Series cannot link up with EDR-G903 models. <p>Changes:</p> <ol style="list-style-type: none"> 1. Renamed RSTP transparent to RSTP Grouping. 	N/A
v4.2	Build_17022316	N/A	PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV	<p>New Features: N/A</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A
v4.1	N/A	N/A	PT-G503-PHR-PTP-HV, PT-G503-PHR-PTP-WV	<p>New Features:</p> <ol style="list-style-type: none"> 1. First release for PT-G503 Series. <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A