

**Software Name:** Firmware for Moxa Remote Connect Suite (MRC Gateway)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
2.0	Build19013119	N/A	MRC-1002-LTE-US-T, MRC-1002-T	<p><b>New Features:</b> N/A</p> <p><b>Enhancements:</b> 1. Reduced system traffic bandwidth consumption.</p>	<p><b>Bugs Fixed:</b> 1. DNS always shows the default DNS. 2. In order to activate changes to the tunnel control, the DUT needed to be rebooted. 3. Gateway could not change network scenario from Cellular-WAN mode. 4. LTE gateway showed the wrong WAN IP address.</p> <p><b>Changes:</b> N/A</p>	For gateway with FW 1.1, to upgrade firmware to V2.0, please upgrade to FW 1.3 first and then upgrade to FW 2.0 to avoid connection error. For FW v1.3, please contact with your local sales/FAE.
1.3	N/A	N/A	MRC-1002-LTE-US-T, MRC-1002-T	<p><b>New Features:</b> Enhance LTE connection and activation speed.</p> <p><b>Enhancements:</b> N/A</p>	<p><b>Bugs Fixed:</b> Additional data transmission when turning service off on MRC Server.</p> <p><b>Changes:</b> N/A</p>	N/A