

**Software Name:** Driver for NPort 5200 Series (Windows Driver Manager)

| Version No. | Build Date No./ Release Date | Supported OS  | Apply to Models | New Features/ Enhancements  | Bugs Fixed/Changes  | Note  |
|-------------|------------------------------|---|-----------------|---|---|---|
| 2.0         | N/A                          | Windows_95,<br>Windows_98,<br>Windows_98,<br>Windows_ME,<br>Windows_Vista,<br>Windows_XP,<br>Windows_NT,<br>Windows_2000,<br>Windows_Server_2003,<br>Windows_Server_2008,<br>Windows_ME,<br>Windows_NT,<br>Windows_XP,<br>Windows_2000,<br>Windows_98,<br>Windows_Server_2008,<br>Windows_95,<br>Windows_Vista,<br>Windows_Server_2003,<br>Windows_98 | N/A             | <p><b>New Features:</b><br/>N/A</p> <p><b>Enhancements:</b><br/>Upgraded OpenSSL Library.</p> | <p><b>Bugs Fixed:</b></p> <ol style="list-style-type: none"> <li>1. Fixed the network timeout issue in NPort Windows Driver Manager.</li> <li>2. TCP port 60950 and 60966 are occupied even when not in use.</li> <li>3. Serial port mapping might fail on some antivirus software.</li> </ol> <p><b>Changes:</b><br/>Divided driver into separate versions, v2.0 supports Windows 95/98/ME/NT/XP/Vista and Windows Server 2003/2008.</p> | This version is divided into two separate drivers (v2.0 and v3.0) to support different Windows platforms. |