

Software Name: Driver for NPort IAW5000A-I/O Series (Real TTY for Linux 2.4.x, 2.6.x)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
1.19	N/A	Linux_2.4.x, Linux_2.6.x	N/A	New Features:	Bugs Fixed:	N/A
				Added driver background polling feature to eliminate the waiting time when an NPort is not present in Slackware 14.0.	A call trace may happen with the error message "not syncing: Fatal exception" in kernel 2.6 for specific platforms. Compiling error if the kernel version contains the stream "2.4."	
				Enhancements:	3. Real TTY driver installation and uninstallation fails due	
				When using a domain name as the mapping address for NPort, it will be	to insufficient permissions for the /tmp folder. Changes:	
				translated every time when Real TTY is opening the port.	Log file increasing without limit causes a file system	
				2. Compiling errors when using	crash.	
				secured Real COM mode.	2. No longer supports 3.x and above.	