

**Software Name:** Driver for NPort S8000 Series (Windows Driver Manager)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
2.0	N/A	Windows_2000, Windows_95, Windows_XP, Windows_Server_2003, Windows_98_SE, Windows_ME, Windows_NT, Windows_Vista, Windows_Server_2008, Windows_98	N/A	<p><b>New Features:</b> N/A</p> <p><b>Enhancements:</b> Upgraded OpenSSL Library.</p>	<p><b>Bugs Fixed:</b></p> <ol style="list-style-type: none"> <li>1. Fixed the network timeout issue in NPort Windows Driver Manager.</li> <li>2. TCP port 60950 and 60966 are occupied even when not in use.</li> <li>3. Serial port mapping might fail on some antivirus software.</li> </ol> <p><b>Changes:</b> Divided driver into separate versions, v2.0 supports Windows 95/98/ME/NT/XP/Vista and Windows Server 2003/2008.</p>	This version is divided into two separate drivers (v2.0 and v3.0) to support different Windows platforms.