

## Software Name: Firmware for CN2600 Series (CN2610)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
3.1	N/A	N/A	CN2510 Series (CN2510-8 and CN2510-16) and CN2610 Series (CN2610-8 and CN2610-16).	<b>New Features:</b> Supports Redundant COM function for CN2610-8/16. <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> 1. RIP packets could not be sent via PPP or SLIP. 2. AsyncServer's DHCP could only send a DHCP request twice. We modified the DHCP behavior so AsyncServer will continue to send DHCP discover packets if there is no DHCP response. 3. AsyncServer would not save the sender's MAC address if the target IP was not the IP of the CN2600. <b>Changes:</b> N/A	N/A