

Software Name: Firmware for MiiNePort E2 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.4	16112216	N/A	MiiNePort E2, MiiNePort E2-H, MiiNePort E2-T, MiiNePort E2-H-T, MiiNePort E2-ST, MiiNePort E2-H-ST	<p>New Features: N/A</p> <p>Enhancements:</p> <ol style="list-style-type: none"> Prevents XSS attacks on web server. Extended challenge ID to 64 bytes for security purposes. Supports CSRF token on webpage for security purposes. Enhanced web login security and supports 5 users logged in simultaneously. Enabled default password for login. Supports encrypted import/export. Removed the echo server (port 7) function. The "sysDescr" default value is set to the model name. Upgraded MOS kernel to v2.2.33. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Import configuration cannot change input/output mode for DIO 1 in DIO Settings. Console showed DIO state error when DIO mode was set to input. In MCSC mode, MiiNePort may stop sending continuous data when using a slow baudrate. When SNMP was disabled, clients would still get a response from the server. When setting the operation mode to MCSC from another modes through SCM, the wrong response would be received. In TCP client mode, the inactivity time needed at least 1 second to disconnect the server. <p>Changes: N/A</p>	Support MiiNePort E2-SDK, MiiNePort E2-H-SDK
v1.3	11110720	N/A	MiiNePort E2, MiiNePort E2-H, MiiNePort E2-T, MiiNePort E2-H-T, MiiNePort E2-ST, MiiNePort E2-H-ST	<p>New Features:</p> <ol style="list-style-type: none"> Supports MiiNePort SDK firmware. <p>Enhancements:</p> <ol style="list-style-type: none"> If MiiNePort receives a ARP request from another host for which an ARP entry already exists, the hardware address in the ARP entry will be updated accordingly. 	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> RFC1213-MIB "Get Next" of sysServices will get ifIndex instead of ifNumber. <p>Changes: N/A</p>	Support MiiNePort E2-SDK, MiiNePort E2-H-SDK
v1.2	11071409	N/A	MiiNePort E2, MiiNePort E2-H, MiiNePort E2-T, MiiNePort E2-H-T, MiiNePort E2-ST, MiiNePort E2-H-ST	<p>New Features: N/A</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> In Real COM mode, the alive check mechanism would not work properly. <p>Changes: N/A</p>	N/A

Software Name: Firmware for MiiNePort E2 Series

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.1	10080614	N/A	MiiNePort E2, MiiNePort E2-H, MiiNePort E2-T, MiiNePort E2-H-T, MiiNePort E2-ST, MiiNePort E2-H-ST	New Features: 1. First release. Enhancements: N/A	Bugs Fixed: N/A Changes: N/A	N/A