

Software Name: Driver for MiiNePort E2 Series (Windows Driver Manager)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
2.0	N/A	Windows_95, Windows_98, Windows_98_SE, Windows_ME, Windows_Vista, Windows_XP, Windows_NT, Windows_2000, Windows_Server_2008	N/A	<p>New Features: N/A</p> <p>Enhancements: Upgraded OpenSSL Library.</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. Fixed the network timeout issue in NPort Windows Driver Manager. 2. TCP port 60950 and 60966 are occupied even when not in use. 3. Serial port mapping might fail on some antivirus software. <p>Changes: Divided driver into separate versions, v2.0 supports Windows 95/98/ME/NT/XP/Vista and Windows Server 2003/2008.</p>	This version is divided into two separate drivers (v2.0 and v3.0) to support different Windows platforms.