

Software Name: Driver for MiiNePort E2 Series (Windows Driver Manager)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
3.0	N/A	Windows_10, Windows_8.1, Windows_8, Windows_7, Windows_Server_2016, Windows_Server_2012_R2, Windows_Server_2012, Windows_Server_2008_R2	N/A	<p>New Features: N/A</p> <p>Enhancements: Upgraded OpenSSL Library.</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. Fixed the network timeout issue in NPort Windows Driver Manager. 2. When using the NPort 6000 in high security mode in Windows 10, may not be able to open ports. 3. TCP port 60950 and 60966 are occupied even when not in use. 4. Fixed BSOD which occurs when driver cancels pending IRPs. <p>Changes: Divided driver into separate versions, v3.0 supports Windows 7/8/8.1/10 and Windows Server 2008 R2/2012/2012R2.</p>	This version is divided into two separate drivers (v2.0 and v3.0) to support different Windows platforms.