

**Software Name:** Driver for MiiNePort E1 Series (Windows Driver Manager)

| Version No. | Build Date No./ Release Date | Supported OS  | Apply to Models | New Features/ Enhancements   | Bugs Fixed/Changes   | Note  |
|-------------|------------------------------|---|-----------------|--|--|---|
| 2.0         | N/A                          | Windows_95,<br>Windows_98,<br>Windows_98_SE,<br>Windows_ME,<br>Windows_Vista,<br>Windows_XP,<br>Windows_NT,<br>Windows_2000,<br>Windows_Server_2003,<br>Windows_Server_2008 | N/A             | <b>New Features:</b><br>N/A<br><br><b>Enhancements:</b><br>Upgraded OpenSSL Library. | <b>Bugs Fixed:</b><br>1. Fixed the network timeout issue in NPort Windows Driver Manager.<br>2. TCP port 60950 and 60966 are occupied even when not in use.<br>3. Serial port mapping might fail on some antivirus software.<br><b>Changes:</b><br>Divided driver into separate versions, v2.0 supports Windows 95/98/ME/NT/XP/Vista and Windows Server 2003/2008. | This version is divided into two separate drivers (v2.0 and v3.0) to support different Windows platforms. |