## Software Name: Utility for NE-4100 Series (Network Enabler

## Administrator)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.11	Build 07082213	Windows_XP, Windows_Vista	NE-4110S, NE-4120S, NE- 4100T, NE-4110A, NE-4120A, NE-4110S-CMD, NE-4120S- CMD, NE-4100T-CMD, NE- 4110A-CMD, NE-4120A-CMD, WE-2100T-US, WE-2100T-EU, WE-2100T-JP	New Features: N/A Enhancements: N/A	Bugs Fixed: 1. COM Mapping page showed wrong baudrate. 2. Downgraded firmware and an attempt to configure specified NE, "Load Configuration Fail." might occur. Changes: N/A	N/A
v2.10	N/A	Windows_XP, Windows_Vista	NE-4110S, NE-4120S, NE- 4100T, NE-4110A, NE-4120A, NE-4110S-CMD, NE-4120S- CMD, NE-4100T-CMD, NE- 4110A-CMD, NE-4120A-CMD, WE-2100T-US, WE-2100T-EU, WE-2100T-JP	New Features: 1. Supports WE-2100T series. Enhancements: 1. Enable [Monitor], [Port Monitor], and [IP Address Report] initially. 2. Keep device list when rescanning.	<ul> <li>Bugs Fixed:</li> <li>1. [GO] button was enabled when monitoring started.</li> <li>2. [Port Monitor] always shows "Connecting" by TCP Client Mode.</li> <li>3. When more than one monitoring targets were added, only the last target was detected as alive.</li> <li>4. When more than one port monitoring targets were added, only the last target was detected as alive.</li> <li>5. An access violation occurred when more than one NE/WE reported IPs.</li> <li>Changes:</li> <li>N/A</li> </ul>	N/A
v2.9	N/A	Windows_XP, Windows_Vista	NE-4110S, NE-4120S, NE- 4100T, NE-4110A, NE-4120A, NE-4110S-CMD, NE-4120S- CMD, NE-4100T-CMD, NE- 4110A-CMD, NE-4120A-CMD, WE-2100T-US, WE-2100T-EU, WE-2100T-JP	New Features: 1. Configuration export function for Ethernet PHY speed setting. 2. Configuration export function for gratuitous ARP setting. 3. Ethernet PHY and gratuitous ARP setting exclude firmware 4.0.6. 4. RealCOM driver support baudrate up to 921600. 5. Supports Windows Vista. Enhancements: N/A	<ul> <li>Bugs Fixed:</li> <li>1. Adding/removing com256 failed problem.</li> <li>2. Help function not working on Windows Vista problems.</li> <li>3. ioctl of setting Xon/xoff character failed.</li> <li>4. A backward compatible issue that NEAdmin pops up an error message when dealing with firmware before 4.0.2.</li> <li>5. A backward compatible issue that NEAdmin pops up an error message when dealing with the NE-4000 Series.</li> <li>Changes:</li> <li>N/A</li> </ul>	N/A

## Software Name: Utility for NE-4100 Series (Network Enabler

Administrator)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.8	N/A	Windows_XP, Windows_Vista	NE-4110S, NE-4120S, NE- 4100T, NE-4110A, NE-4120A, NE-4110S-CMD, NE-4120S- CMD, NE-4100T-CMD, NE- 4110A-CMD, NE-4120A-CMD, WE-2100T-US, WE-2100T-EU, WE-2100T-JP	<ol> <li>Supports wide temperature hardware.</li> <li>RealCOM driver supports baudrate up to 230400.</li> <li>RealCOM driver supports x64 architecture</li> </ol>	<ul> <li>Bugs Fixed:</li> <li>1. Prevents BSOD on write function because of invalid memory is accessed.</li> <li>2. Stop Bits setting error in Com Port Settings.</li> <li>3. Unable to map COM port with over 130 devices.</li> <li>Changes:</li> <li>N/A</li> </ul>	N/A
v2.7	N/A	Windows_XP, Windows_Vista	NE-4110S, NE-4120S, NE- 4100T, NE-4110A, NE-4120A, NE-4110S-CMD, NE-4120S- CMD, NE-4100T-CMD, NE- 4110A-CMD, NE-4120A-CMD, WE-2100T-US, WE-2100T-EU, WE-2100T-JP	1. First release. Enhancements:	Bugs Fixed: N/A Changes: N/A	N/A