

Software Name: Driver for CP-102E/102EL Series (Windows 2008 or earlier)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.24	N/A	Windows_Server_2008, Windows_XP, Windows_Vista, Windows_2000	N/A	<p>New Features: Supports PC/104 serial boards, including CA-104, CA-132, CA-132I, CA-108, CA-114, CA-134I, CB-108, CB-114, and CB-134I.</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. Data transmission error on Windows 10 for PCIe cards. 2. RTS toggle is not working for PCIe boards. 3. While installing CA/ISA cards, model name may not be found in "Add New Hardware Wizard". 4. The software keeps cancelling read commands, which causes BSOD. 5. When the system boots up with CP134EL-A-I, CP138E-A-I, CP118E-A-I, and CP-116E-A, the serial communication might failed randomly. <p>Changes: Windows XP is not included in WHQL support list due to the updated Windows rule.</p>	N/A