

Software Name: Driver for CP-104EL-A Series (SCO 5)

| Version No. | Build Date No./ Release Date | Supported OS | Apply to Models | New Features/ Enhancements | Bugs Fixed/Changes | Note |
|----------------|---------------------------------|------------------|-----------------|------------------------------|--|------|
| v1.13 | N/A | SCO_OpenServer_5 | N/A | New Features: | Bugs Fixed: | N/A |
| | | | | CP-134EL-A-I, and CP-116E-A. | Driver could not find a board located on a PCI bus number above 15. Changes: N/A | |