

**Software Name:** Driver for CP-168EL-A (Windows XP, 2008 or earlier)

| Version No. | Build Date No./ Release Date | Supported OS  | Apply to Models | New Features/ Enhancements  | Bugs Fixed/Changes   | Note |
|-------------|------------------------------|---|-----------------|---|--|------|
| v1.24       | N/A                          | Windows_2000,<br>Windows_Server_2003,<br>Windows_Server_2008,<br>Windows_Vista,<br>Windows_XP | N/A             | <p><b>New Features:</b><br/>Supports PC/104 serial boards, including CA-104, CA-132, CA-132I, CA-108, CA-114, CA-134I, CB-108, CB-114, and CB-134I.</p> <p><b>Enhancements:</b><br/>N/A</p> | <p><b>Bugs Fixed:</b></p> <ol style="list-style-type: none"> <li>RTS toggle not working for PCIe boards.</li> <li>While installing PC/104 and ISA cards, the model name might not be found when using the "Add New Hardware Wizard".</li> <li>The software kept cancelling read commands, which caused a BSOD.</li> <li>When the system boots up with CP134EL-A-I, CP138E-A-I, CP118E-A-I, and CP-116E-A, serial communication might fail randomly.</li> </ol> <p><b>Changes:</b><br/>Windows XP is not included in WHQL support list due to the updated Windows rule.</p> | N/A  |
| v1.24       | N/A                          | Windows XP,Windows 2000,Windows Vista,Windows Server 2008,Windows Server 2003                 | N/A             | <p><b>New Features:</b><br/>N/A</p> <p><b>Enhancements:</b><br/>N/A</p>   | <p><b>Bugs Fixed:</b><br/>N/A</p> <p><b>Changes:</b><br/>N/A</p>   | N/A  |