

## **Software Name:** Driver for CP-132EL Series (SCO 6)

| Version<br>No. | Build Date No./<br>Release Date | Supported OS     | Apply to Models | New Features/ Enhancements | Bugs Fixed/Changes  | Note |
|----------------|---------------------------------|------------------|-----------------|----------------------------|---|------|
| v1.13          | N/A                             | SCO_OpenServer_6 | N/A             | New Features:              | Bugs Fixed:   | N/A  |
|                |                                 |                  |                 |                            | Driver could not find a board located on a PCI bus number above 15. |      |
|                |                                 |                  |                 | Enhancements:              | Changes:  |      |
|                |                                 |                  |                 | N/A                        | N/A   |      |