

Software Name: Driver for CP-132EL Series (Windows XP, 2008 or earlier)

| Version No. | Build Date No./ Release Date | Supported OS | Apply to Models | New Features/ Enhancements | Bugs Fixed/Changes | Note |
|----------------|---------------------------------|---|-----------------|---|---|------|
| v1.24 | N/A | Windows_2000, Windows_Server_2003, Windows_Server_2008, Windows_Vista, Windows_XP | N/A | New Features: Supports PC/104 serial boards, including CA-104, CA-132, CA-132I, CA-108, CA-114, CA-134I, CB-108, CB-114, and CB-134I. Enhancements: N/A | Bugs Fixed: 1. RTS toggle not working for PCIe boards. 2. While installing PC/104 and ISA cards, the model name might not be found when using the "Add New Hardware Wizard". 3. The software kept cancelling read commands, which caused a BSOD. 4. When the system boots up with CP134EL-A-I, CP138E-A-I, CP118E-A-I, and CP-116E-A, serial communication might fail randomly. Changes: Windows XP is not included in WHQL support list due to the updated Windows rule. | N/A |
| v1.24 | N/A | Windows XP,Windows 2000,Windows Vista,Windows Server 2008,Windows Server 2003 | N/A | New Features: N/A Enhancements: N/A | Bugs Fixed: N/A Changes: N/A | N/A |