

Software Name: Driver for CP-132UL Series (SCO 5)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.13	N/A	SCO_OpenServer_5	N/A	New Features:	Bugs Fixed:	N/A
				, , , , , , , , , , , , , , , , , , , ,	Driver could not find a board located on a PCI bus number above 15.	
				Enhancements:	Changes:	
				N/A	N/A	