

Software Name: Driver for CP-112UL Series (UnixWare)

| Version No. | Build Date No./ Release Date | Supported OS | Apply to Models | New Features/ Enhancements | Bugs Fixed/Changes | Note |
|----------------|---------------------------------|----------------|-----------------|----------------------------|---|------|
| v1.13 | N/A | SCO_UnixWare_7 | N/A | New Features: | Bugs Fixed: | N/A |
| | | | | | Driver could not find a board located on a PCI bus number above 15. | |
| | | | | Enhancements: | Changes: | |
| | | | | N/A | N/A | |