

Software Name: Driver for CA-104 Series (Windows XP, 2008 or earlier)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.24	N/A	Windows_2000, Windows_Server_2003, Windows_Server_2008, Windows_Vista, Windows_XP	N/A	<p>New Features: Supports PC/104 serial boards, including CA-104, CA-132, CA-132I, CA-108, CA-114, CA-134I, CB-108, CB-114, and CB-134I.</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> RTS toggle not working for PCIe boards. While installing PC/104 and ISA cards, the model name might not be found when using the "Add New Hardware Wizard". The software kept cancelling read commands, which caused a BSOD. When the system boots up with CP134EL-A-I, CP138E-A-I, CP118E-A-I, and CP-116E-A, serial communication might fail randomly. <p>Changes: Windows XP is not included in WHQL support list due to the updated Windows rule.</p>	N/A
v1.24	N/A	Windows XP,Windows 2000,Windows Vista,Windows Server 2008,Windows Server 2003	N/A	<p>New Features: N/A</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A