

**Software Name:** Driver for CB-108 Series (WinCE 5)

| Version No. | Build Date No./ Release Date | Supported OS   | Apply to Models | New Features/ Enhancements   | Bugs Fixed/Changes  | Note |
|-------------|------------------------------|----------------|-----------------|--|---|------|
| v1.1        | N/A                          | Windows_CE_5.0 | N/A             | <b>New Features:</b><br>Supports multiple MOXA Smartio/Industio PCI and PC/104-Plus cards.<br><br><b>Enhancements:</b><br>Improved latency time. | <b>Bugs Fixed:</b><br>1. Fixed timeout error when a transaction is busy.<br>2. Fixed errors when setting software flow control.<br>3. Fixed the system not updating modem status immediately.<br>4. Fixed the system hanging when the setting of software follow control is disabled.<br><br><b>Changes:</b><br>N/A | N/A  |