

Software Name: Driver for CB-134I Series (Windows 7, 2008 R2, or later)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.24	N/A	Windows_10, Windows_7, Windows_8, Windows_8.1, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016	N/A	<p>New Features:</p> <ol style="list-style-type: none"> Now supports Windows Server 2016. Supports PC/104 serial boards, including CA-104, CA-132, CA-132I, CA-108, CA-114, CA-134I, CB-108, CB-114, and CB-134I. <p>Enhancements: N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> Fixed data transmission error in Windows 10 for PCIe cards. RTS toggle not working for PCIe boards. While installing PC/104 and ISA cards, the model name might not be found when using the "Add New Hardware Wizard". Software kept cancelling read commands, which caused a BSOD. When the system boots up with CP134EL-A-I, CP138E-A-I, CP118E-A-I, and CP-116E-A, serial communication might fail randomly. <p>Changes: N/A</p>	N/A
v1.24	N/A	Windows 7,Windows 10,Windows Server 2012,Windows 8,Windows Server 2008	N/A	<p>New Features: N/A</p> <p>Enhancements: N/A</p>	<p>Bugs Fixed: N/A</p> <p>Changes: N/A</p>	N/A