

**Software Name:** Driver for CB-134I Series (WinCE 5)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.1	N/A	Windows_CE_5.0	N/A	<p><b>New Features:</b> Supports multiple MOXA Smartio/Industio PCI and PC/104-Plus cards.</p> <p><b>Enhancements:</b> Improved latency time.</p>	<p><b>Bugs Fixed:</b></p> <ol style="list-style-type: none"> <li>1. Fixed timeout error when a transaction is busy.</li> <li>2. Fixed errors when setting software flow control.</li> <li>3. Fixed the system not updating modem status immediately.</li> <li>4. Fixed the system hanging when the setting of software follow control is disabled.</li> </ol> <p><b>Changes:</b> N/A</p>	N/A