

Software Name: OnCell Central Manager Software (32-bit)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.3	Build 17032817	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> 1. RESTful API support. 2. RSSI monitor. 3. IP blocking management. 4. Remote SMS control. 5. Supports G3150A-LTE. 6. Supports Windows 10.  <b>Enhancements:</b> 1. Redesigned the UI layout 2. Account login security. 3. Supports multiple import configurations.	<b>Bugs Fixed:</b> 1. Configuration export fails when an OnCell device disconnects and reconnects.  <b>Changes:</b> N/A	N/A
v2.2	Build 15110610	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> N/A  <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> 1. Authentication Bypass security vulnerability. 2. Import/export configuration failed. 3. Device login failed. 4. Device reboot failed.  <b>Changes:</b> N/A	N/A

Software Name: OnCell Central Manager Software (32-bit)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v2.1	Build 15073111	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<p><b>New Features:</b></p> <p>1. Supports data connection idle timeout.</p> <p><b>Enhancements:</b></p> <p>N/A</p>	<p><b>Bugs Fixed:</b></p> <p>1. When an OnCell device repeatedly tries to reconnect to OCM, the mapping port is blocked.</p> <p>2. A second service forwarding connection cannot be accepted after the current connection is registered.</p> <p><b>Changes:</b></p> <p>N/A</p>	N/A
v2.0	Build 14102818	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<p><b>New Features:</b></p> <p>1. Supports AWK-1127, OnCell G3470A-LTE, and WDR-3124A.</p> <p><b>Enhancements:</b></p> <p>1. Improves the performance of OCM to enable management of more devices (up to 2000 devices on the x64 platform).</p> <p>2. The operation mode mapping port will sometimes change when a device reconnects to OCM.</p>	<p><b>Bugs Fixed:</b></p> <p>N/A</p> <p><b>Changes:</b></p> <p>N/A</p>	N/A

Software Name: OnCell Central Manager Software (32-bit)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.6	Build 11083118	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> 1.Supports "Register as Windows service" function. 2. Support OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell 5004-HSPA, and OnCell 5104-HSPA. <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> N/A  <b>Changes:</b> N/A	N/A
v1.5	Build 11030820	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> 1. Supports OnCell G3110-HSDPA-JPN, OnCell G3150-HSDPA-JPN, OnCell 5004-HSDPA-JPN, and OnCell 5104-HSDPA-JPN. <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> N/A  <b>Changes:</b> N/A	N/A

Software Name: OnCell Central Manager Software (32-bit)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.4.2	Build 11022518	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> N/A  <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> 1. Tomcat server fails to start if the waiting time is more than 20 seconds. 2. The number of connections in the connection pool are not enough when a large number of devices connect to OCM. <b>Changes:</b> N/A	N/A
v1.4	Build 10113016	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> 1. Supports OnCell G3211, OnCell G3251, OnCell 5004-HSDPA-JPS, and OnCell 5104-HSDPA-JPS. <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> 1. OCM will automatically restart the web server when a serious error occurs. 2. Data/packet loss between an OnCell device and OCM could result in connection failure. 3. OCM will create a new log file when the current one exceeds 256 MB. <b>Changes:</b> N/A	N/A

Software Name: OnCell Central Manager Software (32-bit)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.3	Build 10031717	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> 1. Supports user account management. 2. Supports device group management. <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> 1. Upgrade Tomcat server from 6.0.18 to 6.0.24. <b>Changes:</b> N/A	N/A
v1.2	Build 10010720	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<b>New Features:</b> 1. Supports auto transfer of data from current to newer databases. <b>Enhancements:</b> N/A	<b>Bugs Fixed:</b> 1. OnCell devices can't connect to OCM when OCM has been running for a long time. 2. Login failure when OCM has been running for a long time. <b>Changes:</b> N/A	N/A

Software Name: OnCell Central Manager Software (32-bit)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.1	Build 09112511	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<p><b>New Features:</b></p> <p>1. Supports firmware upgrade for multiple devices.</p> <p><b>Enhancements:</b></p> <p>N/A</p>	<p><b>Bugs Fixed:</b></p> <p>1. OnCell Central Manager (OCM) is always shown as being offline. 2. When an OnCell device's WAN IP changes OCM does not display the correct information. 3. Maintenance function is accessible even when the user is not logged in.</p> <p><b>Changes:</b></p> <p>N/A</p>	N/A
v1.0	Build 09073015	Windows_10, Windows_7, Windows_8, Windows_Server_2003, Windows_Server_2008, Windows_Server_2008_R2, Windows_Server_2012, Windows_Server_2012_R2, Windows_Server_2016, Windows_Server_2019, Windows_Vista	OnCell G3110-HSPA, OnCell G3150-HSPA, OnCell G3110-HSPA-T, OnCell G3150-HSPA-T, OnCell G3150A-LTE-US-T, OnCell G3150A-LTE-EU, OnCell G3150A-LTE-EU-T, OnCell G3150A-LTE-US, OnCell G3151, OnCell G3211, OnCell G3251, OnCell G3111, OnCell G3111-HSPA, OnCell G3151-HSPA, OnCell 5104-HSPA, OnCell 5104-HSPA-T, OnCell G3470A-LTE-US, OnCell G3470A-LTE-US-T, OnCell G3470A-LTE-EU-T, OnCell G3470A-LTE-EU	<p><b>New Features:</b></p> <p>1. First release.</p> <p><b>Enhancements:</b></p> <p>N/A</p>	<p><b>Bugs Fixed:</b></p> <p>N/A</p> <p><b>Changes:</b></p> <p>N/A</p>	N/A