



**Software Release Note**

**Software Name: ioAdmin**

Version No.	Build Code	Supported OS	Apply to (full model name)	New Feature(s)	Change(s)	Enhancement(s)	Bug(s) Fixed	Additional Note(s)
3.19	Build14041113	N/A	ioLogik E2210 (-T) ioLogik E2212 (-T) ioLogik E2214 (-T) ioLogik E2240 (-T) ioLogik E2242 (-T) ioLogik E2260 (-T) ioLogik E2262 (-T) ioLogik R2110 ioLogik R2140 ioLogik W5312 ioLogik W5340 ioLogik W5340-HSPA NA-4010 NA-4020/NA-4021	N/A	N/A	1. Using new installshield 2. Allowed 1 Message setting only (i.e. Active message, CGI, E-mail, or SMS) for all THEN or all ELSE actions in one rule.	N/A	N/A
3.18	Build16022511	N/A	ioLogik E2210 (-T) ioLogik E2212 (-T) ioLogik E2214 (-T) ioLogik E2240 (-T) ioLogik E2242 (-T) ioLogik E2260 (-T) ioLogik E2262 (-T) ioLogik R2110 ioLogik R2140 ioLogik W5312 ioLogik W5340 ioLogik W5340-HSPA NA-4010 NA-4020/NA-4021	N/A	N/A	1. Updated device wiring guide 2. Advanced encryption algorithm on password in configuration file for ioLogik E2200 series	1. Fixed unable to set the value of virtual channel from -0.1 to -0.9 for ioLogik W5300 series	N/A
3.17	Build14041113	N/A	ioLogik E2210 (-T) ioLogik E2212 (-T) ioLogik E2214 (-T) ioLogik E2240 (-T) ioLogik E2242 (-T) ioLogik E2260 (-T) ioLogik E2262 (-T) ioLogik R2110 ioLogik R2140 ioLogik W5312 ioLogik W5340 ioLogik W5340-HSPA NA-4010 NA-4020/NA-4021	N/A	N/A	1. Support MOXA green core design 2. W5340-HSPA Model supports SMTP port number changing	N/A	N/A
3.16	Build 14012415	N/A	ioLogik E2210 (-T) ioLogik E2212 (-T) ioLogik E2214 (-T) ioLogik E2240 (-T) ioLogik E2242 (-T) ioLogik E2260 (-T) ioLogik E2262 (-T) ioLogik R2110 ioLogik R2140 ioLogik W5312 ioLogik W5340 ioLogik W5340-HSPA NA-4010 NA-4020/NA-4021	1. New ioLogik W5340-HSPA is supported	N/A	N/A	N/A	N/A
3.15	Build13052215	N/A	ioLogik E2210 (-T) ioLogik E2212 (-T) ioLogik E2214 (-T) ioLogik E2240 (-T) ioLogik E2242 (-T) ioLogik E2260 (-T) ioLogik E2262 (-T) ioLogik R2110 ioLogik R2140 ioLogik W5312 ioLogik W5340-HSPDA NA-4010 NA-4020/NA-4021	1. Support ioLogik E2200-T series model	N/A	1. Improve AutoSearch UI for module selection 2. Restricted Click & Go timer setting range from 0 to 4294967, to prevent error value setting	N/A	N/A
3.14	Build12112118	N/A	ioLogik E2210 ioLogik E2212 ioLogik E2214 ioLogik E2240 ioLogik E2242 ioLogik E2260 ioLogik E2262 ioLogik R2110 ioLogik R2140 ioLogik W5312 ioLogik W5340 ioLogik W5340-HSDPA NA-4010 NA-4020/NA-4021	N/A	N/A	N/A	1. Fix issue while E2242 DIO all select DO, DI setting page not be restricted 2. Fix W5340-HSPDA add expansion modules – modules description error 3. Fix W5340-HSPDA add expansion modules – cannot add ioLogik E1212	N/A