

Software Name: Driver for NPort S9650I Series (Windows XP Embedded)

Version No.	Build Date No./ Release Date	Supported OS	Apply to Models	New Features/ Enhancements	Bugs Fixed/Changes	Note
v1.14	Build 11042017	Windows_XP_Embedded	N/A	<p>New Features:</p> <ol style="list-style-type: none"> 1. Support NPort S8458-4S-SC-T. 2. Support NPort 5600 DTL Series. 3. The NPort driver will open the COM port on the system even if the port is blocked or the Ethernet connection has been disabled. <p>Enhancements:</p> <p>N/A</p>	<p>Bugs Fixed:</p> <ol style="list-style-type: none"> 1. DE-2XX and DE-3XX Series cannot be found when searched for if there are four or more devices. 2. The NPort device cannot be found using utility via a wireless network adapter under Windows Vista/7. 3. The driver causes system BSOD by writing to an invalid memory location under Windows 2008 64-bit. 4. The application will not work properly when logged in with a standard user in a Windows Vista/7 environment. This version will prompt the user to change to an account with admin privileges. <p>Changes:</p> <p>N/A</p>	N/A